

.040" Board to Board Copper Connectors

Spacing and Accessory Chart

Stacking Connectors

Stacking Connector, 130 position, Compression, X388X-100A

Stacking Connector, 130 position, Compression, X3884-000A

Part Number	Board Spacing	Technical Sheet	Accessories Included
3882-100A	.476"	TS0421	Stiffeners #4-40 Flat Head Phillips Machine Screw
3884-000A	.738"	TS0422	Jackscrews
3887-100A		TS0421	Stiffeners #4-40 Flat Head Phillips Machine Screw